



Point Repair #	Start MH	End MH	Start Depth (ft)	End MH Depth (ft)	Total Length of Pipe (ft)	Pipe Diameter (in)	Location Start (ft)	Pipe Material	Problem Summary	Service Position	Pre-CIPP	Repair	Repair Detail	Patch Detail
59	1037-02	1037-01	4.0	4.3	162.2	8	88.5	PVC	Service - Deformed Lateral	10		Pt. Repair (83.5 FT to 93.5 FT) - Install Tee and Lateral	2, 3, & 7	
60	1037-05	1037-04	4.4	4.2	128.4	8	23.6	PVC	Hole - Void Visible			Pt. Repair (18.6 FT to 30.2 FT)	5	11
61	1037-13	1037-12	5.0	5.0	97.2	8	67.2	PVC	Offset Joint - Small			Pt. Repair (62.2 FT to 72.2 FT)	5	
62	611-03	611-03	5.7	5.7	313.2	8	287.3	PVC	Offset Joint - Large			Pt. Repair (282.3 FT to 296.4 FT)	5	
63	611-04	611-03	6.3	5.7	313.2	8	291.4	PVC	Offset Joint - Large			Pt. Repair (282.3 FT to 296.4 FT)	5	
64	611-05	611-10	5.2	-	42.9	6	5.0	PVC	Hole - Void Visible			Replace to ROW	15	10
65	611-07	611-12	5.6	8.0	115.7	8	18.4	PVC	Service - Roots in Lateral	9		Pt. Repair (13.4 FT to 23.4 FT) - Install Tee and Lateral	2, 3, & 7	10
66	611-12	SERV 2	6.6	-	33.6	6	5.0	PVC	Roots at 1 Joint			Replace to ROW	15	10
67	611-12	611-10	6.6	8.0	277.4	8	220.5	PVC	Service - Roots in Lateral	3		Pt. Repair (215.5 FT to 225.5 FT) - Install Tee and Lateral	2, 3, & 7	10
68	611-10	SERV 11	8.0	-	27.8	6	5.0	PVC	Roots at 1 Joint			Replace to ROW	15	10
69	617-09	617-02	6.7	5.4	300.1	8	88.6	PVC	Service - Roots in Lateral	2		Pt. Repair (83.6 FT to 93.6 FT) - Install Tee and Lateral	2, 3, & 7	10
70	617-09	SERV 2	8.7	-	233.4	6	5.0	PVC	4 x 6 Connection - Roots at Connection	2		Replace to ROW	15	10
70.1	617-12	SERV 2	7.6	-	39.9	6	5.0	PVC	Roots at 1 Joint	2		Replace to ROW	15	10
71	517-01	SERV 11	5.1	-	15.1	6	15.1	PVC	4" Diameter Lateral			Replace to ROW	15	14
71	563-06	563-05	5.8	4.3	221.7	8	201.1	VCP	Offset Joint - Medium			Pt. Repair (196.1 FT to 206.1 FT)	5	10

WWW.LDILine.com

Order Plans @

LEGEND

- 699-100 MSSD SANITARY SEWER MANHOLE
- MSSD SANITARY SEWER
- SERVICE LATERALS
- REWA SANITARY SEWER MANHOLE
- - - - - REWA SANITARY SEWER
- - - - - PROPERTY LINE
- EDGE-OF-PAVEMENT
- ▭ BUILDING FOOTPRINT
- STREAM/EDGE-OF-WATER
- NEW SERVICE LATERAL

NOTE:
SERVICE LATERALS ARE SHOWN FOR INFORMATION PURPOSES ARE APPROXIMATELY BASED ON CCTV DATA AND MANHOLE INSPECTIONS. NOT ALL EXISTING SERVICES ARE SHOWN. ALL SERVICES TO BE REPAIRED ARE SHOWN.

[Signature]
1/29/2018



SOUTH GREENVILLE
POINT REPAIR PROJECT

POINT REPAIR 59 - 71

PROJECT	SHEET TITLE	MARK	DATE	DESCRIPTION

Apprvd:	
Date:	1-29-18
Chkd:	JLD
Drwn:	MBL
Scale:	1"=200'
Project Number:	16-4005
Sheet:	C-9