

GENERAL NOTES:

- EXTERIOR AND INTERIOR DIMENSIONS ARE TO FACE OF NEW FINISH UNLESS NOTED OTHERWISE. CONTRACTOR SHALL FIELD VERIFY CLEARANCES PRIOR TO CONSTRUCTION.
- GC TO PROVIDE CLEAR SILICONE SEALANT BETWEEN ALL FINISH MATERIALS
 AND EQUIPMENT (NEW AND EXISTING) INCLUDING KITCHEN AND
 RESTROOM AFEAS AND AT EQUIPMENT NOT SEPARATED MORE THAN 1"
 FROM ADJACENT SURFACES.
- GC TO RE-INSTALL / PROVIDE FIRE EXTINGUISHER (S) TYPE "K" AT KITC MISSING) AND PUBLICLY VISIBLE TYPE ABC IN CABINET AT DINING RQ
- 4. G.C. TO PROVIDE A FINAL CLEANING TO REMOVE ALL I EXTERIOR AND INTERIOR.
- NEW & MOVED ELECTRICAL RECEPTACLE
 EVALUATED AND COORDINATED WITH IN
- EXISTING BUILDING IS TYPE VB -A2 ASSEMBLY OCCUPANCY. 7. G.C. TO PROVIDE ELECTRICAL.
- 8. REPAIR / REPLA
- BUILDING PIPING AS PART OF THIS WORK. EA INSTALL ALL NEW FINISHES ACCORDING TO SPECS ON INCLUDING: PLASTIC LAMINATE WAINSCOT & TRIM; SOLID UNITES: TRIM, CHAIR PAIL & SULIS; WALL AND FLOOP TILE; NTER FASCIA, COUNTERTOP - AND - FRP/TILE @ KITCHEN. TO PROVIDE UNIT PRICING FOR REPLACEMENT OF WALL FOR THE

(TERIOR AND INTERIOR INCLUDING FINISHES, SHEATHING, ETC.) ○ CONSTRUCTION KEYNOTES:

- NEW C.F.C.I. SERVICE COUNTER & LOW SUPPORT WALL BELOW. SEE 3/A1.2 & DECOR DRAWINGS FOR ADDITIONAL INFO.
- GC TO REPLACE / REPAIR EXISTING DAMAGED FLOOR TILE AND BASE THROUGHOUT. RE-GROUT AREAS OF EXISTING TILE TO REMAIN WHERE GROUT IS CRACKED OR MISSING SEE A1.1.
- 3. EXIST, MENU BOARD BULKHEAD ABOVE, GC, TO REMOVE EXIST, MENUS; REMOVE ALL EXIST, FINISHES TO GYP., PATCH & REPAIR GYP TO "LIKE-NEW" CONDITION & REFINISH BULKHEAD BEHIND; THEN RE-INSTALL MENU BOARDS SEE INT. DECOR DRAWINGS FOR FINISH COLORS, PROVIDE NEW SST. CAP ⊚ BASE W/ 1-1/2" EXT. LEGS.
- 4. PROVIDE & INSTALL NEW WAINSCOT, CHAIR RAILS, WINDOW SILLS & PAINT AT DINING ROOM WALLS. REPAIR/ REPLACE ROTTED OR LEAKY SILLS @ WINDOWS AS REQ'D.
- 5. INSTALL NEW DOORS & FRAME IN PLACE OF REMOVED EXISTING DOOR. EXISTING SERVICE DOOR TO REMAIN, PAINT DOOR & FRAMES INTERIOR &
 EXTERIOR. REPLACE PANIC DEVICE, LOCK CYLINDER, ALARM, AND CLOSER
 AS REQUIRED TO RETURN TO WORKING CONDITION.
- GC TO INSTALL NEW CHAIRS, STOOLS, BOOTHS, TABLE-TOPS, SOFT SEATING CHAIRS, COFFEE TABLE, SEATING BENCH, TRASH RECEPTACLES, AND OTHER INTERIOR ELEMENTS AT DINING ROOM SEE INTERIOR DECOR (ID) DRAWINGS FOR FULL SCOPE.
- PROVIDE NEW WALL TILE ® BEVERAGE STATION SEE INT. DECOR

 PROVIDE & INSTALL NEW TILE ® SERVING COUNTER AND CORRIDOR;
 PROVIDE NEW MITL. CORNER & TERMINATION STRIPS, COORD, INSTALLATION
 OF STANLESS STEEL TRIMS AT ALL WALL EQUIPMENT OPENINGS. -SEE ID.
 DRAWINGS
- 10. PROVIDE & INSTALL NEW OFFICE COUNTERS AND SHELVING SEE INT. ELEVATIONS & DECOR DRAWINGS, RE-ROUTE DATA AS REQ'D, PROVIDE NEW ELEC, OUTLETS.
- 11. INSTALL NEW RESTROOM WALL FINISHES, FIXTURES, DOORS, ETC. SEE ENLARGED DRAWING, SHEET A7.1.
- 12. REPAIR / REPLACE EXST. DAMAGED FRP/WALL TILE AS REG'D. IN KITCHEN. HOLES / DAMAGE MEASURING 1"SO. OR LESS MAY BE REPAIRED W/ SEALANT; LARGER AREAS TO BE CUT AND PATCHED W/ NEW SECTIONS OF FRP/TILE. PROVIDE NEW TRIM WHERE TRIM IS MISSING AND/OR DAMAGED.
- 13. REPAIR EXISTING MOP SINK @ THIS LOCATION; PROVIDE FIXTURES & PLUMBING AS REQ'D SEE CORRESPONDING NOTE ON SHEET A1.1.
- PLUMBING AS READ T-SEE CORRESPONDING NOTE ON SHEET ALT.


 1. REPAIR ALL EXIST, STOREFRONT WINDOWS, REPLACE DAMAGED GLAZING
 OR GLAZING WITH BROKEN SEALS (HAZING OR WATER BETWEEN PANES), FILL
 ALL FRAME HOLES WITH SEALANT AND REPLACE RUBBER SEALS WHERE
 DAMAGED TYP, COORD, NEW EXT. FINISHES TO PROVIDE 'CLEAN' FINISHED
 CONDITIONS.
- D.T. BOLLARD; PAINT TO CONTRAST BUILDING BEHIND; IF EXIST, REPAINT; IF MISSING, ADD NEW SEE A0.1 & BOLLARD DTL ON THIS SHEET.
- 16. CONTRACTOR TO PROVIDE NEW WALL SURFACE [CEMENTITIOUS BACKER BOARD SUBSTRATE; FRP/TILE TO MATCH EXIST, AND BASE] AT REMOVED ROTTED PORTIONS OF WALL AT KITCHEN, FIELD VERIFY CONDITIONS SEE

WALL TYPE INDICATION:

 EXISTING PARTITION TO REMAIN NEW PARTITION / EXTERIOR WALL

PARTITION LEGEND:

- . ALL NEW INT. PARTITIONS TO BE TYPE 10 UNLESS NOTED OTHERWISE.
- 2. SEE A3.2 FOR STUD ATTACHMENT / BRACING DETAILS



RTG. DESCRIPTION 5/8" GYP. BD. @ EA. SIDE OF 2X4 WD. STUDS @ 16" O.C. -EXT. 6" ABOVE CEIL. 5/8" GYP. BD. @ EA. SIDE OF 2X6 WD. STUDS @ 16" O.C. -EXT. 6" ABOVE CEIL.

5/8" GYP, BD, SCREWED TO BOTH SIDES OF 2X4 WD. STUDS @ 24" O.C. W/ FULL THICKNESS EXTEND TO 6" ABOVE CEILING

ELECTRICAL NOTES:

- GC TO PROVIDE ALL NEW OUTLETS SHOWN ON ID DRAWINGS.
- GC TO REPLACE ANY CONCEALED POWER STRIPS (ABOVE CEILING) OR OUTLETS W/ ACCESSIBLE SURFACE -MOUNTED OUTLETS.
- 3. GC TO CHECK & PROVIDE GFI OUTLETS @ KITCHEN AREAS IF NOT PROVIDED.
- 4. GC TO CHECK MAIN LUG TORQUE & TO EXERCISE MAIN BREAKER.
- 5. GC TO PROVIDE NEW COVERS @ ALL MISSING COVERS FOR OUTLETS OR PANELS.





