

Architectural specification sheet for 'PART 2 - EXECUTION' and 'SECTION 072100 - THERMAL INSULATION'. The table is organized into columns for different sections and rows for various subsections like '2.1 EXAMINATION', '2.2 UTILITY SERVICES', '2.3 SELECTIVE DEMOLITION', '2.4 CLEANING', 'SECTION 05500 - METAL FABRICATIONS', 'SECTION 06405 ARCHITECTURAL CABINETS...', 'SECTION 072100 - THERMAL INSULATION', and 'SECTION 082100 - THERMAL INSULATION'. Each cell contains detailed technical requirements, materials lists, and quality assurance procedures. A large diagonal watermark 'Order Plans' is overlaid across the entire table.

Architectural specification sheet for '2.3 SHOP PRIMING', 'PART 3 - EXECUTION', 'SECTION 08712 - DOOR HARDWARE', 'SECTION 09260 - GYPSUM BOARD ASSEMBLIES', and 'PART 2 - PRODUCTS'. It details requirements for door priming, hardware installation, gypsum board assemblies, and lists specific product standards for various materials. A large diagonal watermark 'Order Plans' is overlaid across the entire table.



2000 SHAWNEE MISSION PARKWAY
STE 100 MISSION WOODS, KS 66205
TEL 816 502 1500 FAX 816 842 1878

Sprint
#1641 WHITEHAVEN PLAZA
4088 ELVIS PRESLEY BLVD.
SUITE 104
MEMPHIS, TENNESSEE 38116

MATTHEW MASLIONS - ARCHITECT
TENNESSEE # 102630

I have prepared the drawings and assume responsibility for the sheets numbered with an "A" prefix for the project named below.
Other drawings and specifications attached for the above-mentioned project have been by and are the responsibility of the licensed engineer whose stamp and firm appear on that sheet.
The architect is not responsible for the design of the mechanical, electrical, plumbing, civil, landscaping, structural, signage (not specified), fire sprinkler or fire suppression systems, and does not take responsibility for the compliance of these areas with the laws of the above governmental entities. The architect is not responsible for certification, during construction or upon completion of construction. The architect is not responsible for improper operation due to faulty installation or product failure during construction or after completion of construction when operation has begun for the landfill or tenant.
The licensed professional whose stamp appears on sheets other than those specifically noted above shall be responsible for those items in paragraph three.

Revision table with columns for 'NO.', 'DATE', and 'DESCRIPTION'.
1. _____
2. _____
3. _____

SHEET TITLE

SPECIFICATIONS

PROJECT NUMBER: 2017014-006
SHEET NUMBER: 08
DATE: JANUARY 5, 2017

SHEET NUMBER: **A02**

RMTA.BIZ