

GENERAL NOTES:

1. PATCH OPENINGS AT NEW ROOF EQUIPMENT. REPAIR ROOFING MEMBRANE. OBTAIN LANDLORD APPROVAL FOR ROOF REPAIR PRIOR TO COMMENCING WORK.

KEY NOTES:


1. EXHAUST FAN, SEE MECH.
2. CONDENSING UNIT FOR WALKIN BEER COOLER.
3. CONDENSING UNIT FOR WALKIN FREEZER.
4. CONDENSING UNIT FOR WALKIN COOLER.
5. RTU, SEE MECH.
6. MAKEUP AIR UNIT, SEE MECH.
7. DEMISING WALL, SEE MECH.
8. CORRUGATED METAL ROOF.
9. SHIPPING CONTAINER ROOF.
10. GUTTER AND DOWNSPOUT.

1. GUTTER AND DOWNSPOUT AT WEST SIDE OF SHIPPING CONTAINER.

CONSULTANT:

JOHN SPONSELLER, ARCHITECT

8025 W. 25TH PL.
LAKEWOOD, CO 80214
TEL: (303) 815-0161



GOOD TIMES RESTAURANTS, INC.
141 Union Blvd., Suite 400
Lakewood, CO 80228
303-384-1430

BAD DADDY'S BURGER BAR
"EASTCHASE"
THE VENUE EASTCHASE
NWC EASTCHASE PKWY &
EASTCHASE LN.
MONTGOMERY, AL 36117

Issue Record:

4.23.2019	FOR PLAN REVIEW

Revisions:

5.6.2019	WALKIN BOX
7.1.2019	CANOPY REVS
2.10.2021	TO GO REVS

Drawn:
DRAWN BY: JS, KC

Checked:
CHECKED BY: JS

Project No.
PROJECT#: 19-207

Contact:

ROOF PLAN

A150

Date of Last Print:
2.10.2021

Order Plans @

WWW.LDILine.com